





E9




E252



E21




E46




E81



E094



E30




E79



E168



E159



E156



E072

■ Pattern book  
Vzorník potahových látek  
Bezugsstoffe-Musterbuch

## Xtreme

Composition/Složení/Zusammensetzung	100% Polyester Xtreme FR	
Weight/Váha/Gewicht	434 g/lm	
Width/Šířka/Breite	140 cm	
Abrasion resistance/Oděruvzdornost/Scheuerfestigkeit	Martindale	100 000
Light fastness/Stálobarevnost na světle/ Lichtechtheit	6	ISO 105-B02
Fastness to rubbing/Stálobarevnost v otěru/Reibechtheit	4	ISO 105-X12
Piling/Žmolkování/Piling	5	BS EN ISO 12945-2
Flammability/Ohnivzdornost/Feuersicherung	(GB) CRIB 5, (D) B1	EN 1021/1-2

- For standard care regularly use vacuum cleaner. Clean with damp cloth.
- Pro běžné čištění a údržbu pravidelně vysávejte vysavačem. V případě potřeby čistěte hadříkem navlhčeným vodou.
- Zur standardmäßigen Pflege bitte regelmäßig absaugen. Reinigen Sie den Stoff mit einem feuchten Tuch.